

Creative services | Restoration sample


Project details

Window description

- 27-1/8" x 42-7/8" (68.9 cm x 108.9 cm)
- Leaded panel in clear glass texture with jewels
- Bevel cluster in centre

Pre-restoration condition

- Antique lead severely deteriorated
- Window sagging in frame
- Central bevel cluster popping out
- Broken oval bevel in central cluster
- Broken glass sections



Scope of work


- Securely remove window from residence
- Create a rubbing of original window for reconstruction purposes




- Dismantle window under **conservation safety guidelines**




- Wash all glass to remove detritus
- **Environmentally recycle** old lead



- Reconstruction includes replacement of broken glass, custom beveling, reinforced lead for verticals for hidden support and replacement of rebar



- Glazing
- Apply patina and polish



Contact us:

For more information on our creative services, whether custom, repair, or restoration, please contact us at:

Glasstronomy Studios
2600 John St., Unit 108
Markham ON L3R 3W3

t 1.855.415.9777
e cs@glasstronomystudios.ca
w glasstronomystudios.ca